

SB: Wall - mounted hose boxes

Article : 8023, 8024, 8025



Reason: Incompatibility of the wall bracket hole pattern from the old models art. 2648 and 2656 to the new wall-mounted hose boxes:

Solution: The wall bracket art. 8023-00.900.03 has a different hole pattern compared to wall bracket 2648-00.600.21 . For service cases, when an old hose box art. 2648 or 2656 is changed into the new one (art. 8023, 8024 , 8025), an adapter plate is available to fix the bracket to the old holes :



The adapter plate with screws and dowels is available as a spare part with part no. 8023-00.650.06.