

# Illustrated Parts List - IPL Update



Product Name(s)

**CS2260/CS2260WH**

Description of change

1. Piston, assy (D46) : 584 80 78-06 was 584 80 78-02. Piston profile and ovality have been changed to minimize piston seizures.
2. Cylinder, assy with piston 575 35 58-05 was 575 35 58-03. Piston and needle bearing changed.
3. New Crankshaft 575 54 52-09 with improved grip. New ball bearings and needle bearing.
4. New Ball bearings 525 43 42-02 and 505 13 35-02.
5. New Needle bearing 503 25 63-02.

Comments

This update is fully exchangeable.

Introduced from

Serial number / Date	Remark
s/n 20154500217	Cylinder – Piston
s/n 20154500097	Valid for Bearings and Crankshaft.
s/n 20153300001	Valid for 503 25 63-02 Needle bearing.

IPL updates

Page Title	Ref. no	New part no	Name	Excl. part no.	Remark
Cylinder Piston	7	575 35 58-06	Cylinder, assy	575 35 58-04	
	8	584 80 78-06	Piston, assy	584 80 78-02	
	11	503 25 63-02	Needle bearing	501 45 16-01	Remain as spare part.
Crankshaft	1	575 54 52-09	Crankshaft, assy	575 54 52-05	
	2	505 13 35-02	Ball bearing	505 13 35-01	
	3	525 43 42-02	Ball bearing	525 43 42-01	Remain as spare part.
	4	503 25 63-02	Needle bearing	501 45 16-01	Remain as spare part.